# **ORDERING INFORMATION FOR PROBE NEEDLES**

#### **Probe Material**

Tungsten = W Tungsten-Rhenium = WR

Beryllium-Copper = BC (silver-plated)

 $\begin{array}{lll} \text{NewTek}^{\text{\tiny{TM}}} = & \text{NTK} \\ \text{VerTek}^{\text{\tiny{TM}}} = & \text{VTK} \\ \text{Paliney-}7 \circledR = & \text{P} \\ \end{array}$ 


#### **Platings and Coatings**


Nickel = NP (W and WR only) Silver = AP (W and WR only)

Tin-Dipped (60Sn-40Pb) = TD (all materials)
TIP-M™ Insulation = TIPM (all materials)

#### **Etch Length Finish**

Polish = All materials Matte = (W and WR only)






Below are examples of how to specify part numbers for probe needles.

## To order a SHARP TIP:





### To order a RADIUS TIP:



